

Wound Healing, Case 2

Figure 5 shows the left lower leg of a 57 year old male patient with chronic ulcer before the first shock wave treatment. Since one year a conservative therapy with various dressings has been applied without success.



Fig. 5

Figure 6 shows the lesion of the same patient 2 weeks later before the second shock wave treatment.



Fig. 6

Figure 7 shows the patient after 2 more weeks when the dressing was changed. No more therapy was necessary at that stage.



Fig. 7

Figure 8 shows the healing status 6 weeks after starting the therapy after overall 2 shock wave treatments. In total, the 2 treatments lasted less than five minutes.



Fig. 8.